

Typical Characteristics




Fig. 1 Power Derating Curve








Fig. 2, Typical Forward Characteristics



UNIT	A	B	b _p	C	D	E	H _ε	A ₁	L _p
mm	1.40	2	0.50	0.19	3.10	1.65	3.00	0.100	0.50
	0.95		0.35	0.08		1.20			